



State of Utah
DEPARTMENT OF NATURAL RESOURCES
Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report
Minerals Regulatory Program
September 6, 2007

Supervisor RRH

Mine Name: Antelope Quarry
Operator Name: Bown Stone Products.

Permit number: S/039/018
Inspection Date: August 29, 2007
Time: 10:30 am

Inspector(s): Lynn Kunzler, DOGM
Other Participants: none
Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:

Routine inspection while in the area.

Inspection Summary:

This operation received permit approval on March 2, 2007, and was amended on August 16, 2007 to include a second pit on the northern boundary of the SITLA lease area. At the time of this inspection, a two-track road has been made to the location of the second pit and a small quarry has been started. (less than 1/10 of an acre so far). A track-hoe and an air compressor were located at this site. Both pits were free of trash. Less than 3 acres of disturbance exists on this site (permitted for 5 acres).

A GPS was used to identify the location of Pit #2 and the access road between the two pits.

Photos were taken to document site conditions.

Conclusions and Recommendations:

There were no non-compliance issues observed at this site. Continue to monitor this site when in the area.

Inspector's Signature

LK:pb

O:\M039-Sanpete\S0390018-Antelope\inspections\Insp-08292007.doc